RYFRAME°

Dry Tech Reversible Liner Ladies'Jacket



DF7651L

Product Features:

- Exterior/Reversible Side: 1.8-oz, 100% nylon taffeta
- Fill: 3.9-oz, poly-fill
- Drawcord and toggles at hem
- Reflective RYFRAME logo on bottom left hem on quilted and smooth side
- Reverse coil zippered hand pockets on quilted side
- Detachable carabiner keychain located in left hand
- Reverse coil zippered right chest pocket on smooth side
- Locker loop on smooth side
- 3-panel hood with spandex binding

Ladies' sizes: XS-4XL

Icons/Fabric Features:

















Available Colours and PMS Colours

Textile fabric colours are subject to dye lot variation and will not be exact match to print pantone reference



WARMTH RATING	MILD	● WARM	WARMER	WARMEST		
WATER PROTECTION	● WATER	RESISTANT	WATERPROOF			
. WIND RESISTANT	YES					
INSULATION	3.9-OZ, SYNTHETIC INSULATION					

428C / BLACK 6C

DF7651L - DRYFRAME® Dry Tech Reversible Liner Ladies' Jacket

GARMENT MEASUREMENTS								
Size	XS	S	М	L	XL	2XL	3XL	4XL
Chest - Half Measure	18"	19"	20"	21 1/2"	23"	24 1/2"	26 1/2"	28 1/2"
Chest - Full Measure	36"	38"	40"	43"	46"	49"	53"	57"
Body Length from HPS (At Front)	24 1/2"	25"	25 1/2"	26 1/2"	27 1/2"	28 1/2"	29"	29 1/2"
Body Length from HPS (At Back)	25"	25 1/2"	26"	27"	28"	29"	29 1/2"	30"
Sleeve Length-CB	32"	32 1/2"	33"	33 1/2"	34"	34 1/2"	35"	35 1/2"

Finished measurements in inches. Refer to "How to Measure" guide for detailed information on measurement instructions.

LADIES' General Sizing Guide								
Size	xs	S	М	L	XL	2XL	3XL	4XL
Numeric Size	2	4-6	8-10	12-14	16	18-20	22	24
Bust	32"-34"	35"-36"	37"-38"	39"-41"	42"-44"	45"-47"	48"-51"	52"-55"
Waist	24"-25"	26"-27"	28"-30"	30"-32"	33"-35"	36"-38"	40"-42"	42"-44"
Hip	33"-35"	35"-37"	37"-39"	39"-41"	42"-44"	45"-47"	48"-50"	50"-52"
Sleeve Length-CB	30"-30 1/2"	30 1/2"-31"	31 1/2"-32"	32 1/2"-33"	33 1/2"-34"	34"-34 1/2"	34 1/2"-35"	34 1/2"-35"



PRINTING INSTRUCTIONS FOR NYLON FABRICS

Due to the nature of Nylon fabric, special care must be taken throughout the decoration process. Special care must be taken during the decoration process and after.

Here are some tips to effectively decorate these products.

Heat Transfer/Screen Printing:

- Garment temperature must not exceed 310°F or 154°C.
- Use fast fushion/low cure temperature ink to help prevent the need for a higher temperature to cure the ink.
- A test sample run is recommended in all printing processes, especially if you have a large order or if your printer does not specialize in